



FIT Walk Program is a day-long plant walk where APEX fastening experts evaluate your plants' fastening processes.

○ ⊕ ○ ≎ ⊗ ⊗ ઙ



FLIP FOR FIT WALK PROCESS INFORMATION



The Fastening Improvement Team (FIT) Walk Program is a plant walk focused on optimizing your plant's workflow by evaluating your fastening applications and usage. The FIT Walk Program is ideal for facilities interested in fastening improvements, cost-saving opportunities, safer workspace, or educational training for your team.

The FIT Walk will start with a meet & greet with your fastening engineer, followed by 5 to 6 hour assembly line analysis. During this analysis our FIT team will walk your assembly line, going through each station to look for cost savings opportunities, custom solution possibilities, misfit, safety issues, and application issues.

After assessment, the FIT team will meet with your fastening engineers to give a brief overview of what was found and have a general discussion on opportunities for improvement. The FIT Team will present a more formal recommendation/proposal to your team within a week.



What is Fastening Improvement Team (FIT)? The Fasting Improvement Team or FIT for short, is a tailored team comprised of Apex assembly & fabrication experts. The purpose of the team is to conduct extensive plant walks to inspect the fastening process.

A FIT WALK WILL...

- IDENTIFY MISAPPLIED FASTENING TOOLS
- IDENTIFY FASTENING TOOLS THAT SHOULD HAVE PROTECTIVE COVERS
- IDENTIFY SAFETY ISSUES (TAPED SOCKETS, INCORRECT SIZES, WORN SOCKETS, ETC)
- IDENTIFY WHERE CUSTOM SOLUTIONS WOULD INCREASE SAFETY AND HIGHER EFFICIENCIES
- IDENTIFY WHERE HAND TOOLS ARE BEING USED IN PLACE OF SAFER INDUSTRIAL POWER TOOLS
- CONSOLIDATION OF THE NUMBER OF NECESSARY SOCKETS AND BITS



SCAN or CLICK the QR CODE to REQUEST YOUR FIT WALK today!